

Michael O. Leavitt Ted Stewart **Executive Director** James W. Carter Division Director 801-538-5319 (TDD)

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax)

November 8, 1993

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer and

Travis Jones, Hydrologist

RE:

Site Inspection, Yankee Mine, S/049/022, Utah County, Utah

Date of Inspection:

November 5, 1993

Time of Inspection:

1625 - 1700

Conditions:

Cold, lightly snowing

Participants:

Tony Gallegos, Travis Jones, DOGM

Purpose of Inspection: To examine the site disturbances and become familiar with

the site

A light cover of snow was on the ground upon our arrival. This snow cover in combination with additional snow falling did not allow us to spend much time at the site. The road into the site is not an all weather road and was already becoming slick in spots.


We examined what we believed was the project area. The snow cover made it difficult to discern which disturbances were associated with this project. A stream of water from a collapsed portal was running through rust colored sediments. The water has some green moss-like vegetation growing in it. The stream then flows over mine waste dump material before joining another stream. Photos were taken of the areas visited.

jb

James Warr, Yankee Mine cc:

S49-22.INS





SOUPLOZE BEAM
DETAIL OF WATER IN STREAM
NEAR COMAPSED PORTAC SEES



68-92 1208888883 Z Ž

S/OH9/OZZ LOCK WG POWWOMFFW FROM LOWER ROAD



E.

SOMY/OZZ

REAM FROM COMAPSED PORTACE

1756



SOMY/OZ ESSAD

•





s/ondlozz

LOWER POAD (SEE TRUCK) 1183885

.

SAN


;



9/049/027

LIOWER ROAD & STREAM CROSSING

NOTE PILE OF WHERLY IN RIGHT FOREGROUND



YOU SO ENMADENENT

·